






A		8x40	x26
B		7x50	x20
C		7x70	x4
D		57/12,5x5,5 Zn	x4
E		M6x8x15x15	x4
F		M6x55	x4
G		M6x80	x16
H		6,3x80	x8
J		M6x10x13	x16
K		M10x12	x4
L		D15x19	x4
M		D9,8x37/60/5,8x23	x4
N		3,5x40	x6
P		D4x13	x24
R		D15x18	x32
Q		D20	x12
S		17x3	x8
T		38x3	x4
U		4mm	x2

①




A		8x40	x26
---	---	------	-----



G		M6x80	x4
H		6,3x80	x2
J		M6x10x13	x4


R		D15x18	x6
Q		D20	x2
T		38x3	x2



G		M6x80	x4
H		6,3x80	x2
J		M6x10x13	x4


R		D15x18	x6
Q		D20	x2
T		38x3	x2

④




G		M6x80	x2
H		6,3x80	x2
J		M6x10x13	x2
R		D15x18	x4

⑤



G		M6x80	x2
H		6,3x80	x2
J		M6x10x13	x2
R		D15x18	x4

⑥





M

D9,8x37/60/5,8
x23

x4

⑦



C



7x70

x4

P





D4x13

x4

8




4mm


G		M6x80	x4
J		M6x10x13	x4
K		M10x12	x4

L		D15x19	x4
R		D15x18	x4
Q		D20	x8

9




4mm

B		7x50	x8
P		D4x13	x8
S		17x3	x4

10


4mm






D		57/12,5x5,5 Zn	x2
E		M6x8x15x15	x2

F		M6x55	x2
R		D15x18	x4

11





B		7x50	x12
P		D4x13	x12
S		17x3	x4



B		7x50	x2
---	--	------	----


12



D		57/12,5x5,5 Zn	x2
E		M6x8x15x15	x2

F		M6x55	x2
R		D15x18	x4

13



N		3,5x40	x6
---	--	--------	----